

POINT FRAME PINS

To enable the pins to pass freely through the frame, the ends have to be a blunt point. Please warn users about taking care with the pins. The top of the pins should have a black rubber cover completely over the end to prevent accidental injuries. If the cover has come off do not use the pin. Spare self adhesive heat shrink sleeving has been supplied with these pins so that any loosened caps can be replaced.

POINT FRAME PINS

To enable the pins to pass freely through the frame, the ends have to be a blunt point. Please warn users about taking care with the pins. The top of the pins should have a black rubber cover completely over the end to prevent accidental injuries. If the cover has come off do not use the pin. Spare self adhesive heat shrink sleeving has been supplied with these pins so that any loosened caps can be replaced

POINT FRAME PINS

To enable the pins to pass freely through the frame, the ends have to be a blunt point. Please warn users about taking care with the pins. The top of the pins should have a black rubber cover completely over the end to prevent accidental injuries. If the cover has come off do not use the pin. Spare self adhesive heat shrink sleeving has been supplied with these pins so that any loosened caps can be replaced

